



## **Duty cycle thermal limit**



These curves are for guidance under standard industrial conditions (ambient temperature 20°C etc.) and correct maintenance (lubrication etc.). They are based on the ZIMM standard trapezoidal thread Tr 120x16. The operation cycles can be many times longer, when using ball screws.


## **Screw jack mounting Z-Series**



## Full rated load (tension and compression)

The gearbox can accept the full static rated load. If the fixing screws are subject to tensile loads, the gear unit can only be loaded to the nominal static load if the additional blind tapped holes (Face F) are used.

The permissible load depends on the type of fastening.



loads are permissible.